ACCESSORIES ANALOG & DIGITAL GAUGES

	Description	Dimensions
G5 2.1/2" Gauge 500 PSI Increment GA1 Gauge Adaptor	 The G5 is a high quality compact liquid filled gauge that reads in both PSI and Bar. Liquid filled to dampen needle vibration, the G5 is perfect for applications up to 10,000 psi. Liquid filled dampens needle vibration. 1% full scale accuracy. 500 psi increment. Stainless steel casing. 	2.50" 2.50"2
G6 4" Gauge 500 PSI Increment G6 4" Gauge Adaptor	 The G6 is a larger, easy to read liquid filled gauge that's in both PSI and Bar with increments of 500 psi. The calibrated scale reads from 0-10,000 psi with 10,000 psi to 15,000 psi as a warning zone. Liquid filled dampens needle vibration. ±1% full scale accuracy. Large easy to read 4" face. Rubber blowout plugs for safety. Stainless steel casing. 	4.00"
G7 4" Gauge G7 5 Gauge G7 4" Gauge G7 4" Gauge GA1 Gauge Adaptor	 The G7 is a larger, easy to read liquid filled gauge that's in both PSI and Bar with increments of 100 PSI/10bar. The calibrated scale reads from 0-10,000 psi. Liquid filled dampens needle vibration. ±1% full scale accuracy. Large easy to read 4" face. Rubber blowout plugs for safety. Stainless steel casing. Standard on all Simplex Torque Wrench Pumps. 	4" 4" 1/4" NPT
GD1 2 1/2" Digital Gauge GA1 Gauge Adaptor	 The GD1 is designed for the high cycle pressure application where mechanical gauges don't hold up. The GD1 is a direct mount, compact gauge with an all stainless steel sensor that is vibration & shock resistant. Self powered Lithium batteries. Full 4 digit display. ±.25% full scale accuracy. 10 million cycle life minimum. 	2.66" 5/8" 5/8" 1/4" NPT
GD2 4" Digital Gauge	 The GD2 digital gauge combines the best features of analog and digital instruments. The 0.75" high full 4 digit display is easily read at a distance and the "analog" bar graph allows instant estimation of changing pressures. The all stainless steel sensor is vibration and shock resistant. 0.75" characters and 270° bar graph "analog" readout. Splash proof phenolic housing. ±.25% full scale accuracy. Keypad enable/disable of peak high or peak low hold. 	5.45" 1.33" 7/8" Flats 1/4" NPT
GA1 Gauge Adaptor	GT25 0 - 25, 55, 100 All 25, 55 & R GT30 0 - 30, 50, 100 4 30 Ton Model GT100 0 - 100, 150, 200 RDA100 & 200	RLS 50 Ton Models FS & RLS 100 Ton Models s, 50 & 100 RLR & RLN D Series, RLR & RLN 150 & 200
Tonnage Gauge		on RC & RCD Series O Ton RC & RCD Series